## UNCLASSIFIED

# AD NUMBER AD029711 CLASSIFICATION CHANGES TO: unclassified restricted FROM: LIMITATION CHANGES TO: Approved for public release, distribution unlimited FROM:

Distribution authorized to DoD only; Foreign Government Information; 10 DEC 1953. Other requests shall be referred to British Embassy, 3100 Massachusetts Avenue, NW, Washington, DC 20008.

# **AUTHORITY**

DSTL, AVIA 18/4112, 30 Jul 2008; DSTL, AVIA 18/4112, 30 Jul 2008

# Armed Services Technical Information Agency

Because of our limited supply, you are requested to return this copy WHEN IT HAS SERVED YOUR PURPOSE so that it may be made available to other requesters. Your cooperation will be appreciated.

NOTICE: WHEN GOVERNMENT OR OTHER DRAWINGS, SPECIFICATIONS OR OTHER DATA ARE USED FOR ANY PURPOSE OTHER THAN IN CONNECTION WITH A DEFINITELY RELATED GOVERNMENT PROCUREMENT OPERATION, THE U. S. GOVERNMENT THEREBY INCURS NO RESPONSIBILITY, NOR ANY OBLIGATION WHATSOEVER; AND THE FACT THAT THE GOVERNMENT MAY HAVE FORMULATED, FURNISHED, OR IN ANY WAY SUPPLIED THE SAID DRAWINGS, SPECIFICATIONS, OR OTHER DATA IS NOT TO BE REGARDED BY IMPLICATION OR OTHERWISE AS IN ANY MANNER LICENSING THE HOLDER OR ANY OTHER PERSON OR CORPORATION, OR CONVEYING ANY RIGHTS OR PERMISSION TO MANUFACTURE, USE OR SELL ANY PATENTED INVENTION THAT MAY IN ANY WAY BE RELATED THERETO.

Reproduced by DOCUMENT SERVICE CENTER KNOTT BUILDING, DAYTON, 2, 0HIO



# Best Available Copy

NOTICE: THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 and 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.



THE RECIPIENT IS WARNED THAT INFORMATION CONTACTED IN THIS DOCUMENT MAY BE SUBJECT TO PRIVATELY-OWNED RIGHTS.

TO BE HANDLED AS U.S. CONFIDENTIAL (par lf, A/S Ltr' 46-53, 3 Dec 53)



16th Part of No. AAEE/871

CONFIDENTIAL

### MINISTRY OF SUPPLY

# AEROPLANE AND ARMAMENT **EXPERIMENTAL ESTABLISHMENT**

### BOSCOMBE DOWN

CLASSIFICATION CHANGED

CONFIDENTIAL

MAY 1 2 1954

#### GANNET A.S. MK.1 - TEST FUSELAGE

#### HOOD JETTISON TESTS IN THE BLOWER TUNNET

THIS INFORMATION IS DISOLOSED FOR OFFICIAL USE BY THE RECIPIENT GOVERNMENT. DISCLOSURE TO ANY OTHER GOVERNMENT OR RELEASE TO THE PRISS OR IN ANY OTHER WAY WOULD BEA BREACH OF THIS COND. TION. THE INFORMATION SHOULD BE SAFFGUARDED UNDER RULES DESIGN D TO GIVE THE FASTE STANDARD OF & CURRY AS THAT MAINTAINED BY HER MAJESTY'S GOVERNMENT IN THE UNITED KINGDOM.

THE INFORMATION CONTAINED IN THIS REPORT HOULD BOT BE CHICULATED OUTSIDE GOVERNMENT DEPARTMENTS WITHOUT THE PRIOR PERMISSION OF THE MINISTRY OF SUPPLY.

ATTENTION IS CALLED TO THE PENALTIES ATTACHING TO ANY INFRINGEMENT OF THE OFFICIAL SECRETS ACT.

#### THIS DOCUMENT IS THE PROPERTY OF H.M. GOVERNMENT.

It is intended for the use of the recipient only, and for communication to such officers under him as may require to be acquainted with the contents of the report in the course of their duties. The officers exercising this power of communication will be held responsible that such information is imparted with due caution and reserve Any person other than the authorised holder, upon obtaining pessession of this document, by finding or otherwise, should forward it, tegether with his name and address, in a closed envelope to :-

THE SECRETARY, MINISTRY OF SUPPLY.

Letter postage need not be prepaid : other postage will be refunded.

All persons are hereby warned that the unauthorised retention or destruction of this document is an offence against the Official Secrets Acts, 1911-1939.

10|51 (A1068) Wt.8856|1527. 32M. 2. 5|52

#### RESTRICTED

16th Part of Report No. AAEE/871

#### AEROPLANE AND ARMAMENT EXPERIMENTAL ESTABLISHMENT POSCOMBE DOWN

10. DEC. 1953

#### Gannet A.S. Mk.1 - Test Fuselage

Hood Jettison Tests in the Blower Tunnel

A. & A.E.E. Ref.: AAKE/6225/T/24/EGW

31/10/52 **-** 3/11/52 9/12/52 **-** 30/12/52 Period of Test :

#### Progress of issue of Report

Report No.	Title					
11th Part of AAEE/87	Representative of the Production Aircraft					
12th - do -	VR.546 Handling Trials of a Prototype nearly Representative of the Production Aircraft					
13th - do -	VR.546 Handling Trials of a Prototype nearly Representative of the Production Aircraft with Cockpit Canopies Removed and also					
14th - do -	vith two External Depth Charges. VR.546 Longitudinal Stability Measurements of a Prototype nearly Representative of the Production Aircraft.					
15th - do -	VR.557 Clearance of Prototype Armament Equipment Designed for Gannet AS Mk.1 and of Certain Other Stores.					

#### Summary

A large number of hood jettison tests have been carried out on the Gannet AS Mk.1 Test Fuselage in the Blower Tunnel.

In the early tests, the hoods failed to release from their hinges until they had pitched through too great an angle, causing them to strike the airframe. As a result of modification the jettison characteristics were improved and all three hoods should jettison satisfactorily in flight at 240 knots. At 115 knots there is a slight danger of the rear hood hitting the fin. The other two hoods are satisfactory at 115 knots. All the hoods pitch very rapidly after release and, if this pitching could be reduced, very much better jettisons could be expected. Flight jettison tests on the middle hood are recommended. Further brief jettison tests, in the blower tunnel, are recommended to ascertain the effect of the aerial wire on the rear two hoods.

This report is issued with the authority of

Air Commodore,

Commanding, A. & A.E.E.,

/Introduction....

#### 1. Introduction

Tests were required to assess the jettison characteristics of the three hoods fitted to the Gannet A.S. Mk.1, and the possibility of injury to the crew or damage to the aircraft in the event of emergency jettisons being made in flight.

All tests were carried out using the structural test fuselage which had been suitably modified to make the hood jettison system and layout representative of a production aircraft. Fig. 1 shows the fuselage prepared for tests in the Blower Tunnel.

#### 2. Description of the hoods and jettison mechanisms

- 2.1. All three hoods were of broad 'U' section constructed of a single skin of transparent material with metal edges. They varied slightly in shape and size but all weighed approximately 45 lbs. (including rails). They moved fore and aft on rollers located in the rails which were attached to the top decking of the fuselage. The No.1 (Pilots) hood was normally opened and closed by means of a hydraulic jack but this was not fitted for these tests. The other two hoods were opened and closed manually and held in either position by locking pins.
- 2.2. Each hood rail was located on the fuselage at the forward end by a hook which engaged with a pin on the underside of the rail. The rear end of each rail was held in position by the hinge fitting.
- 2.3. Operation of the jettison handle caused the hooks to disengage and the front end of the rails were lifted by the action of jettison assister springs. The hood and rails pitched through an angle of 15° before the rear hinges disengaged, and were then free to lift away from the fuselage.
- 2.4. Figs. 2, 3 and 4 show details of the three hood mechanisms as fitted to the test fuselage.
- 2.5. After test 3 the rail hinges were modified to ensure that they could disengage after the hood had pitched through 15°, even if there was no load acting forwards in the rails, as might result from centrifugal loads.

#### 3. Conditions and results of tests

- 3.1. The fuselage was placed in front of the Blower Tunnel in the flight attitude for the test airspeed. The tunnel was set level and was raised and lowered as required to give a good airflow over and around the hood being tested. The fuselage was moved as required when carrying out tests in which yaw was being applied. The 6 ft. diameter nozzle was fitted to the tunnel for all tests.
- 3.2. All tests were recorded photographically from the beam and upper frontal positions. The beam view record incorporated a spark time base and an indication of the exact instant of the jettison handle being pulled.
- 3.3. Rescue slings were fitted to the hoods for all tests to enable them to be used for more than one test.
- 3.4. The aerial mast was not fitted for any of the tests due to the danger of smashing the pilots hood. It was not considered that the aerial wire would have any appreciable effect on the flight path of the hoods, but it would have been tested if there had been any hoods left at the end of the trial.
- 3.5. Details of the tests carried out and the results obtained are given in Appendix  $\Lambda_{\bullet}$

/3.6....

- 3.6. On a number of tests, both at 115 and 240 knots, the hood skins developed small cracks, which seemed to radiate from the corners, but this is not considered a hazard.
- 3.7. Figs. 5 to 22 show the hoods as they started to lift, being freed from the hinges and subsequent positions in flight and the time taken to assume these positions from the instant of pulling the jettison handles.
- 3.8. Attempts were made to move the C.G. of the hoods forward by the addition of lead weights at the front end of the rails. A maximum of 7 lbs. was added and this gave no improvement in jettison characteristics.
- 3.9. The pressures within the cockpits were measured at both 115 knots and 240 knots, with hoods fitted, and the following changes from static were recorded:-

Speed	No. 1 (Pilots)	No. 2 (Obs.)	No. 3 (Aircrew)
115 knots	+ .050 p.s.i.	Zero	Zero
240 knots	+ .125 p.s.i.	Zero	Zero

#### 4. Criticisms of the jettison mechanism

- 4.1. The hinges as fitted to the fuselage for tests 1 to 3 failed to release until the hoods had pitched through too great an angle. This was due to the fact that an end load in the rail in the rearward direction was required to effect a satisfactory release. The modified hinges as fitted for tests 4 to 19 allowed the rails to disengage after the hood had pitched through 15°, no end load being required.
- 4.2. The jettison mechanisms were very simple, easy to maintain and re-set, and no difficulties were experienced during any of the tests carried out.

#### 5. Conclusions

Provided that the new type hinges are fitted, the following conclusions are made:-

- 5.1. All three hoods are likely to jettison satisfactorily in flight at 240 knots.
- 5.2. At 115 knots (1.2  $V_S$ ) there is a slight danger of the rear hood hitting the fin. The other two hoods are satisfactory at 115 knots.
- 5.3. The hoods pitch very rapidly after release, probably due to a combination of aerodynamic and dynamic characteristics. If this pitching could be reduced, very much better jettisons could be expected. Moving the C.G. forward  $1\frac{1}{4}$  inches seemed to have little or no effect.
- 5.4. The pilots hood would have fouled the existing length (20.7°) aerial mast.
- 5.5. The absence of one or two hoods does not materially affect the jettison characteristics of the third hood.
- 5.6. The application of small angles of yaw does not materially effect the jettison characteristics.

#### 6. Recommendations

6.1. The modified rail hinges should be fitted.

- 6.2. Efforts should be made to reduce the angle through which the hoods pitch on being juttisoned, particularly the rear hood, to improve its jettison characteristics at low speed. In the meantime, the Service should be advised to jettison the rear hood at the highest possible speed, or alternatively to open it rather than jettison it at low speeds.
- 6.3. The top of the aerial mast should be swept back at least 3 inches and possibly more. Should a longer aerial mast be adopted, the sweepback will have to be considerably greater. The overall length of the aerial wire attachment fittings must be kept to a minimum to avoid contact with No. 2 hood when jettisoned.
- 6.4. Flight tests are recommended and it is suggested that they are confined to the middle hood. The rear hood should be removed for these tests which should be carried out at 240 knots without the application of yaw. The aerial wire should be removed.
- 6.5. Further brief jettison tests should be carried out, in the blower tunnel, with the aerial wire fitted.


#### Circulation List


A.D.R.D.N. 2 copies, 1 for Action 75 copies 4 copies


Gannet A.S. Mk.1

Fig.	ري.	9	N/A	7	ω.	6	9	Ŧ	12	13	144	15	16
Remarks	Hood lifted at front and pitched through an angle of 43° before releasing from the hinges. It then continued to pitch over on to its back and struck the fuselage, at the point where the fin is normally attached, and broke up.	Hood pitched through 380 before releasing from its hinges. It continued to pitch while passing upwards and aft.	After pitching through a considerable angle the starboard rail disengaged from its hinge and the port rail grayed in engagement. It then yawed to port and the port hinge disengaged and the hood lifted clear of the airframe and hit the top decking between Nos. 2 and 3 cockpits and broke up. The port hinge was found to be distorted after the test. No photographic record is available.	Rail hinges modified. See Para. 2.5.  Hood pitched through 24. before releasing from its hinges. It continued to pitch whilst moving upwards and aft.	Results very similar to Test 4 except that the hood climbed more steeply whilst moving aft.	Results similar to Test 5.	Results as Test 6.	Results as Test 5.	Results as Test 6.	Results identical to Test 4.	Hood lifted at the front and pitched through 26° before releasing from the hinges. It continued to pitch whilst climbing and moving aft.	Results very similar to Test 11.	
Hood 3	Jettison	OFF	OFF	Jettison	OFF	ÆĒO	Fitted	Fitted	Fitted	Jettison	Jettison	<u>ज</u> म्	ጥቷህ
Hood 2	Fitted	Jettison	OFF	Fitted	Jettison	OFF	Fitted	Jettison Fitted	配0	OFF	Fi tted	Jettison	GEE
Hood 1	Pitted	Fitted	Jettison	Fi tted	Fitted	Jettison	Jettison	Fitted	Jettison	OFF	Fitted	Fitted	Jetti son
Yaw	Zero	E	=	=	=		=		=		*	=	=
Incidence	°2+	F	Ė	<b>.</b>	n	ı	2	<b>.</b>	=	=	0.0 4	t	Ē
Speed	တ		<b>s</b>	±	ŧ	#	ŧ	<b>#</b>	#		240 kmcts	#	<b>E</b>
Test	-	N-	. <b>r</b>	4	5	9	7	8	6	10	.5.	12	13

Fig. No.		17	48	19.	. ;	8	21		22
Remarks		Results very similar to Test 11.					Results similar to Test 11 except that the hood rolled slightly		
Hood 3	77001	Jettison	OFF	C Tart	T.FO	Fitted	Jettison		OFF
ı			letti son	E C	OFF	Fitted Jetti son			Fitted Jettison
112.23 4 HOOR 9	1000	100 Port Fitted Fitted	Fitted Lettison		Jet th soil	Fitted .	Fitted Fitted		Fitted
	Iaw	100 Fort	E	:		Zero	50.	3 10.7	=
	Incluence	<sup>2</sup> / <sub>4</sub>				w[4	ŧ		=
-	Speed	1), 115 knots	=			17 240 knots	ŧ		, <b>E</b>
	Test	4	, u		16	17	18		6







115 KTS. NO YAW. DATUM ANGLE TO AIRFLOW +7°

S.M. CH. M. JEMNINGS.

2






FIG. 6 TEST 2. 115 KTS. NO YAW. DATUM ANGLE TO AIRFLOW +7°






GANNET AIS. MK.

871

IST PART OF REPORT NOA&A.EE.

SKNPA4345






FIG.II TEST BILL KTS NO YAW




FIG. IZ TEST 9 IIS KTS NO YAW






FIG. 13 TEST 10 115 KTS, NO YAW.







FIG. 14 TEST II 240 KTS. NO YAW.







くる。これ




Fig. 19 Test 16. 115 kts. 10° port.




FIG.20 TEST 17 240 KTS. NO YAW. (TIMES INDICATED ARE FROM INITIAL MOVEMENT OF HOOD).




FIG. 21 TEST 18 240 KTS, 5° YAW TO PORT. (TIMES INDICATED ARE FROM INITIAL MOVEMENT OF HOOD).




FIG. 22 TEST 19 240 KTS. 5° YAW TO PORT. (TIMES INDICATED ARE FROM INITIAL MOVEMENT OF HOOD).



Information Centre Knowledge Services [dstl] Porton Down Salisbury Witts SP4 04Q 22060-6218 Tel: 01980-613753 Fay 01980-613970

Defense Technical Information Center (DTIC) 8725 John J. Kingman Road, Suit 0944 Fort Belvoir, VA 22060-6218 U.S.A.

AD#: AD029711

Date of Search: 30 July 2008

Record Summary: AVIA 18/4112

Title: Gannet AS Mk 1: test fuselage: hood jettison tests in the Blower Tunnels

Availability Open Document, Open Description, Normal Closure before FOI Act: 30 years

Former reference (Department) 871 Pt 16 Held by The National Archives, Kew

This document is now available at the National Archives, Kew, Surrey, United Kingdom.

DTIC has checked the National Archives Catalogue website (http://www.nationalarchives.gov.uk) and found the document is available and releasable to the public.

Access to UK public records is governed by statute, namely the Public Records Act, 1958, and the Public Records Act, 1967. The document has been released under the 30 year rule. (The vast majority of records selected for permanent preservation are made available to the public when they are 30 years old. This is commonly referred to as the 30 year rule and was established by the Public Records Act of 1967).

This document may be treated as <u>UNLIMITED</u>.